

SOUTHEASTERN DISTRICT HEALTH DEPARTMENT  
INDIVIDUAL SEWAGE DISPOSAL INSTALLATION PERMIT

Permit No. T2-73B Date 1-11-73  
Installation for Virgil Buzget at in 56114 SW 14 55 T6S R34E  
(Name) (Legal description of property)

Address of Installation Chubbuck Rd (Armitong)

No. Living Units 1 Bedrooms 3 People Served \_\_\_\_\_ Water Supply--Private  Public \_\_\_\_\_ Applicant is: Owner  Contractor \_\_\_\_\_ Other \_\_\_\_\_  
FHA \_\_\_\_\_ FARM HOME  VA \_\_\_\_\_ CONV. \_\_\_\_\_ EXISTING \_\_\_\_\_ NO. \_\_\_\_\_

Septic Tank 1000 gal. Perc. Rate \_\_\_\_\_ Min./in. Min. Depth to Ground Water \_\_\_\_\_ ft.  
Effluent Disposal: Effective Area Required 350 sq. ft. Soil System: Soil Profile Gravel & sand  
Field Drain \_\_\_\_\_ Absorption Bed \_\_\_\_\_ Standard  Modified \_\_\_\_\_ Seepage Pit  Dimensions 10x12

Distance from Disposal Area to:  
Property Lines: Front 90 ft. Back 300 ft. Side 50 ft. Dwelling Foundation 5 ft. Well 100 ft.  
Surface Water \_\_\_\_\_ ft. Nearest Neighbor's Well 100 ft. Plot Plan Submitted and Approved  Septic Tank 10 ft.

Remarks: 1.1 Acres  
Applicant Virgil Buzget Paid \_\_\_\_\_ Bill \_\_\_\_\_ No Fee   
Address 43 SE Lewis Postville Ia Permit Issued by Jerem Solomon

INSPECTION: Septic Tank Size \_\_\_\_\_ Standpipe \_\_\_\_\_ Depth to Manhole \_\_\_\_\_  
Distance from Septic Tank to: Dwelling Foundation \_\_\_\_\_ ft. Well \_\_\_\_\_ ft. Nearest Neighbor's Well \_\_\_\_\_ ft.

Effluent Disposal: Effective Area \_\_\_\_\_ sq. ft.  
Field Drain \_\_\_\_\_ Absorption Bed \_\_\_\_\_ Standard \_\_\_\_\_ Modified \_\_\_\_\_ Seepage Pit \_\_\_\_\_ Dimensions \_\_\_\_\_  
Pipe Size \_\_\_\_\_ No. of Lines \_\_\_\_\_ Length \_\_\_\_\_ Depth \_\_\_\_\_

Distance from Disposal Area to:  
Property Lines: Front \_\_\_\_\_ ft. Back \_\_\_\_\_ ft. Side \_\_\_\_\_ ft. Dwelling Foundation \_\_\_\_\_ ft. Well \_\_\_\_\_ ft.  
Surface Water \_\_\_\_\_ ft. Water Service Piping \_\_\_\_\_ ft. Depth to Gravel \_\_\_\_\_ ft. Nearest Neighbor's Well \_\_\_\_\_ ft.

Approved  Not Approved \_\_\_\_\_ Inspected 4-7-73 by Paul Cleaver Installed by Jerem Coffin  
(Date)

Remarks: not complete but after enough along (materials & construction) that it looks OK when completed this afternoon.  
Applicant's sketch of house, proposed sewage layout and all adjacent wells (dimension between all components)

